

My Company Name




My Address

To: Pals Motel

Project: ESA

Bore Hole Log

Project Number: M0-09-1473
Report Number: 1
Report Date: 9/20/01
Contractor: SOIL
Drill Method: AUGER
Technician: MB
Logged By: LS
Drill Date: 9/22/01
Bore Hole Number: 1
Location: Pals Motel
Hole Depth: 7.5 meters
Page: 1 of 1

Meters	Feet	Soil Description	Well Diagram	Symbol	Headspace Vapor (ppm)				
					10	100	1K	10K	100K
1	1	SILT, clay, damp to moist, low plastic, grey	:sand to 5 meters :50 mm solid schd. 40 PVC to 3.0 meters :50 mm 0.01" horizontally slotted schd. 40 PVC from 3.0 meters :bentonite to 7.5 meters :Water level on 9/21/01, 6.5 meters						
	2								
	3								
	4								
	5				160				
2	6	CLAY, silty, moist, low to medium plastic, grey							
	7								
	8								
3	9								
	10				160				
	11								
4	12								
	13								
	14								
5	15				180				
	16								
6	17								
	18								
	19								
7	20				200				
	21								
	22								
	23								
	24								