

My Company Address

To: Remedy, LLC
 95072 Hwy 89
 P.O. Box 1036
 Al, Wy 83110

Project: Geotechnical Investigation- LDS
 Church, Revelstoke, B.C.

Project Number: M01-06-1349
 Report Number: 17
 Report Date: 6/25/01
 Contractor: SOIL
 Drill Method: Solid Stem
 Technician: 1
 Drill Date: 6/19/01
 Bore Hole Number: 17
 Location: Revelstoke, B.C.
 Logged By: L Sarker
 Ground Elevation: 725.656
 Hole Depth: 2.45

Page: 1 of 1

Meters	Moisture					Soil Description	Symbol	Sample	N	Feet	Well
	■ Liquid Limit (%)	● Natural Moisture (%)	▲ Plastic Limit (%)								
	%	10	20	30	40	TOPSOIL OR ORGANIC SOIL					
1						SILT, clayey, calcareous, damp to moist, low to medium plastic, firm, grey to yellowish grey.				1	:sand to 0.5 meters :50 mm solid schd. 40 PVC cc to 1.5 meters :bentonite to 2.0 meters :50 mm 0.01" horizontally slotted schd. 40 PVC from 1.5 meters :Water level on 24-May-19, 1.75 meters :Well depth 2.0 meters
2								14		2	
										3	
										4	
										5	
										6	
										7	
										8	

Plate Number: 1

SPT Sample