

My Company Name


My Address

To: G AND B PROPERTIES LTD
c/o MARTIN MALL
3292 ONCEMORE ROAD, S.E.
MARTINTOWN

Project: MATERIALS TESTING SCOTIA BANK BUILDING.

Sieve Analysis Report

Project Number: M95-10-267
Report Number: 2
Report Date: 13-Mar-96
Copies To: CLIENT
Sample Type: PRG
Sampled By: SGI/WS
Source: STEEPROCK
Tested By: SGI/WS
Sample Date: 13-Mar-96
Date Received: 13-Mar-96
Date Tested: 13-Mar-96



75mm MINUS PIT RUN GRAVEL

Per: _____