

# My Company Name

My Address


# Hydrometer Analysis Report

To: Lafarge Inc.  
Box 727  
149 - Veiner Road  
Brooks

Patrick Humphreys

Project: 2003 Materials Testing  
Brooks shop

Project Number: M03-01-2019  
Report Number: 1  
Report Date: 1/16/2003  
Sampled By: Client  
Tested By: EGT  
Sample Date: 1/8/2003  
Date Received: 1/9/2003  
Date Tested: 1/15/2003



Due to the percentages of granular on cohesive material, this soil is classified as a sandy clay. Based on these results and the Safety Codes Council & Alberta Private Sewage Systems Standard of Practices (1999), the soil is not suitable for disposal fields without further testing.

Per: \_\_\_\_\_